Fig. 2


DRIVE SIGNAL
SIGNAL MISSING DUE TO TOUCHING
OUTPUT SIGNAL
t