
Start
Determine that a first radio unit that is associated with a first radio sector is not active
505
Determine that at least a second radio unit associated with a second sector is configured for at least one of multi-input multi-output and cyclic delay diversity
510
Determine that at least one condition is met indicating the feasibility of the second radio unit for providing service to the first sector and the second sector
515
Disabling the multi-input mutli-output or cyclic delay diversity configuration in the second radio unit
520
Reconfiguring a few of the multi input multi output or cyclic delay diversity configuration ports that are associated with the first radio unit to provide service in the second radio sector for the first radio unit
525
End

Figure 5