
399
PROVIDE UE CAPABILITY INFORMATION
390
RECEIVE, BY CONNECTED MODE UE, MEASUREMENT CONFIGURATION
392
PERFORM BY UE MEASUREMENTS WITH RELAXED PERFORMANCE REQUIREMENTS, SO THAT CARRIERS MORE THAN 3 CAN BE IGNORED OR PERFORMED VIA BEST EFFORTS
310

FIG. 3B