

FIG. 5A



FIG. 5B

600

25F SCAP Charging Method	Max. Voltage	Max. Energy
Continuous charging	1.2 V	18 J
Hysteretic charging- mode boost charger with optimum hysteresis window	≥ 2.5 V	≥ 78.125 J

FIG. 6