
UE REPORTED PCI WITH MORE THAN ONE TARGET CELL MAPPING TO THE SAME PCI IN THE NRT
810
PERFORM AoA
820
RANGE MET BY TARGET IN NRT
828
RANGE NOT MET BY TARGET IN NRT
825
PERFORM HO
860
HANDOVER FAILED, TUNING OF AoA etc NEEDED
870
UPDATE THE AoA etc IN NRT TO EXCLUDE THE FAILURE RANGE
880
PERFORM ANR AS AoA etc RANGE IS NOT MET
830
NEW TARGET
840
NO
YES
PERFORM HO AND UPDATE AoA etc FOR TARGET IN NRT
845
ADD NEW TARGET IN NRT, PERFORM HANDOVER
850

FIG.8