Fig.2



GR
- GREEN REGION G1: BOARD BASE REGION COATED WITH RESIST (RESIST REGION WITH LOWER BRIGHTNESS)
- GREEN REGION G2: COPPER WIRINGS REGION COATED WITH RESIST (RESIST REGION WITH HIGHER BRIGHTNESS)

GOLD REGION GL: REGION PLATED WITH GOLD

BROWN REGION BR: REGION OF BOARD BASE

WHITE REGION WH: REGION PRINTED WITH WHITE CHARACTERS