FIG. 7


RADIAL DIRECTION
7 BINDING TAPE
1 ROTOR
4 FIELD WINDING
20a
CONNECTED LOCATION
STRAIGHT LINE
LENGTH h
20b
CONNECTED LOCATION
6 NEUTRAL RING
CIRCUMFERENTIAL
DIRECTION
3 ROTOR IRON CORE
10 SUPPORTING PORTION

FIG. 8


RADIAL DIRECTION
7 BINDING TAPE
1 ROTOR
4 FIELD WINDING
20a
CONNECTED LOCATION
20b
CONNECTED LOCATION
6 NEUTRAL RING
CIRCUMFERENTIAL
DIRECTION
3 ROTOR IRON CORE
10 SUPPORTING PORTION