
124
Path
Description
AT
Buffer
CGARcp
Intlk
Press
PurgeFlow
Services
SlitCHA
SlitCHB
118
122
Insert
Home
PgUp
Del
End
PgDn
116
<<
V
>>
@JobType01
WAFER_MOVE_STEP_FAILED
Description
Chamber Flags
Job control entry
Job status info
Job step completed
Recipe step comple
Current Job Protoc
Current Job Type
120
OK
Cancel
110

FIG. 7A


116
124
Path
AT/CASS_A/AmatFiLoadPort1.wManCommand
Description
Manual Load Port Commands
122
System
VacRo
VacSy
Wafer
CASS_A
AmatF
CASS_B
CASS_C
CASS_D
118
Insert
Home
PgUp
Del
End
PgDn
<<
V
>>
Name
Description
wCommand
Load Port Comman
wManCommand
Manual Load Port C
wFACommand
Factory Automation
wE87PortXferState
Load Port E87 Xfer
rCmdPending
Load Port Comman
rCmdResult
Load Port Comman
rLastCmdStr
Last Command Strin
rLastCmdRspStr
Last Command Res
120
OK
Cancel
110

FIG. 7B