
Receive information indicative of a calibration skin resistance measurement
1402
Setting a designated resistance range based on the calibration skin resistance measurement
1404
Receive information indicative of a first skin resistance measurement indicative of absence of skin contact between a wear surface electrode sensor and a non-wear surface electrode sensor
1406
Receive information indicative of a second skin resistance measurement indicative of skin contact between the wear surface electrode sensor and the non-wear surface electrode sensor
1408
Determine that the second skin resistance measurement is within the designated resistance range
1410
Determine a user input based on the designated resistance range
1412

FIG. 14