FIG. 8


START
DIVIDE CAPTURED IMAGE INTO A PLURALITY OF SUB BLOCKS
S810
CALCULATE REPRESENTATIVE VALUES AND SET TARGET VALUE
S820
CALCULATE CALIBRATION VALUES
S830
TRANSMIT CALIBRATION VALUES
S840
END