
500
DETERMINE DESIRED COMPRESSION GRADIENT ALONG GARMENT
510
DETERMINE ADDITIONAL COMPRESSIVE FORCE NEEDED AT POINTS ALONG GARMENT TO ATTAIN DESIRED COMPRESSION GRADIENT
520
DETERMINE AMOUNT OF ELASTOMER NEEDED AT POINTS ALONG GARMENT TO ATTAIN DESIRED COMPRESSION GRADIENT
530
FORM TEXTILE FOR GARMENT
540
PRINT NEEDED AMOUNTS OF ELASTOMER ON GARMENT TO ATTAIN DESIRED COMPRESSION GRADIENT
550
FORM PRINTED TEXTILE INTO GARMENT
560

FIG. 5.