- Coupon was heat treated, no sol coating
- Coupon tested for hot corrosion for 1000 hr
  - 960 C, 1 atm, 17% H_2O, 2.5% O_2, 23% CO_2, bal N_2





Fig. 1